



RRVARC New & Improved Repeater Upgrades




146.760 Repeater Connections

As of this time the repeater is not connected to any other systems.

Adding these connections will require a repeater controller with a minimum of 4 ports.

The controller we have along with the expansion board will provide 5 ports.



444.500 Repeater Cross-connect


146.760 Repeater (Self)

444.500 Repeater Connections

As of this time the repeater is connected to the Allstar node only.

Adding the connection to the 146.760 repeater can be done with our existing controller.

No additional hardware is required for the 444.500 repeater.



146.760 Repeater Cross-connect

444.500 Repeater (Self)